



DEPARTMENT OF CIVIL ENGINEERING
GOVT. ENGINEERING COLLEGE, THRISSUR – 9

Ph: 0487-2322989

14.01.2022


STRUCTURAL STABILITY REPORT OF EXISTING BUILDING AT TIRURKAD (AZHAR ENGLISH SCHOOL, TIRURKAD, VALAMBOOR VILLAGE, ANGADIPPURAM GRAMA PANCHAYATH, WARD NO. 3, SURVEY NO. 67/1, 69/9, 69/10, BUILDING NO. III/576 (New –XI/262) MALAPPURAM DISTRICT

As Per the request letter from The Manager, Azhar English School, Tirurkad, I have visited the School building site. I have inspected one building. It is of (G+2) Floors only. It is found that the structural members such as columns are found intact. Non-structural cracks were also not observed on the walls. No cracks were seen on these structural members. Upon Non-destructive (Rebound hammer) testing the structural concrete having designed strength. From the inspection & NDT testing the all buildings are found to be safe under Normal Weather Conditions.

However the following points are noted in connection with the above.

1. Need of safety certificate from fire department is not checked.
2. The other construction quality aspects, especially construction joints, construction of walls etc. are not checked in this investigation
3. In future, any new crack found in the structure, the same should be consulted to a structural engineer and the necessary measures should be taken.
4. The Confirmation for KMBR/KPBR of the Building has not been verified




P P Sivan
Assistant Professor in Civil Engineering

P P Sivan, M.E (Structures)
Assistant Professor in Civil Engg.
Govt. Engg. College Trichur
Thrissur- 680 009
Mob.9809631256
Email-ppsivan@yahoo.com